

# HISTORIC AMERICAN ENGINEERING RECORD

## Index to Photographs

Addendum to:

Hacienda Azucarera Santa Elena:  
Sugar Mill Ruins  
1.44 miles north of PR Route 2  
bridge over Rio de la Plata  
Toa Baja  
Municipality of Toa Baja  
Puerto Rico

HAER No. PR-6

NOTE: These photographs are U.S. Government materials and not subject to copyright. However, the courtesy of a credit line identifying the Historic American Engineering Record and the photographer, Jack Boucher, would be appreciated. All photos were taken in August 1977 by Jack Boucher.

- |         |   |
|---------|---|
| PR-6-1  | View of E elevation of sugar mill looking W.                              |
| PR-6-2  | Skewed view of E elevation of sugar mill looking NW.                      |
| PR-6-3  | Detail view of third bay in E elevation of sugar mill looking W.          |
| PR-6-4  | Detail view of fourth bay in E elevation of sugar mill looking W.         |
| PR-6-5  | Detail view of fifth bay in E elevation of sugar mill looking W.          |
| PR-6-6  | Detail view of eighth bay in E elevation of sugar mill looking W.         |
| PR-6-7  | 3/4 view of sugar mill looking NW showing entry ramp, S and E elevations. |
| PR-6-8  | View of S (front) elevation showing entry ramp.                           |
| PR-6-9  | View of entry ramp on S (front) elevation.                                |
| PR-6-10 | Detail view of right bay of S (front) elevation.                          |
| PR-6-11 | Detail view of cornice on SE corner of mill.                              |
| PR-6-12 | Detail view of molding at second floor level on SE corner of mill.        |
| PR-6-13 | Detail view of belt course on SE corner of mill.                          |
| PR-6-14 | Detail view of molding at first floor level on SE corner of mill.         |

- PR-6-15            View of left bay of N (rear) elevation looking SW.
- PR-6-16            View of middle bay of N (rear) elevation looking SE.
- PR-6-17            Detail view of corner of middle bay of N (rear) elevation looking SE.
- PR-6-18            View of W elevation of ramp looking NE showing entrances and openings to storage spaces below.
- PR-6-19            View of W elevation of mill looking NE showing two bays and wall buttress.
- PR-6-20            Detail view of brick wall buttress on W elevation.
- PR-6-21            View of N room of mill looking NW through arched passageway in wall separating N and S rooms.
- PR-6-22            Detail view of arched passageway as in preceeding photo.
- PR-6-23            Detail view of brickwork in same arched passageway.
- PR-6-24            View of N room of mill looking NE through arched opening in W elevation.
- PR-6-25            View of interior E wall of N room of mill.
- PR-6-26            Sharply angled view looking N at E wall of N room of mill.
- PR-6-27            View of interior S wall of N room of mill showing rows of cast-iron columns and arches.
- PR-6-28            Detail view of small triangular openings (perhaps for ventilation) in top of S wall in center bay of N room of mill.
- PR-6-29            Detail view of small triangular openings from opposite side of wall.
- PR-6-30            Interior view of N room of mill, looking NW, showing cast-iron columns and arches.
- PR-6-31            Closer-in interior view of N room of mill, looking NW, showing cast-iron columns and arches.
- PR-6-32            Symmetrical view of cast-iron columns and arches, looking W, in interior of N room of mill.

PR-6-33 Interior view of N room of mill, looking NW, showing interior of W wall and cast-iron columns and arches.

PR-6-34 Detail view of cast-iron column in N room of mill.

PR-6-35 Detail view of cast-iron column capitol showing bearing point of arches.

PR-6-36 Detail view of base of cast-iron column.

PR-6-37 Detail view of center of cast-iron arch in N room of mill.

PR-6-38 View of niche in center bay of N room in mill ruins in which a painting or tapestry of Santa Elena was hung.

PR-6-39 View of S room looking SW.

PR-6-40 View of S room looking NW.

PR-6-41 Detail view of brick column and arch in S room.

PR-6-42 View of S room looking SE.

PR-6-43 Detail view of connection between column top and arch in S room.

PR-6-44 Detail view of column capitol and arch in S room.

PR-6-45 View of end bay of W elevation showing openings in wall associated with sugar making process.

PR-6-46 View of end bay of NW corner of mill ruins showing where flue emerged from area of Jamaican Train.

PR-6-47 View of E interior wall of S room.

PR-6-48 Detail of top of wall in S room showing strap-iron beam tie-back anchored in wall with severely deteriorated beam in place.

PR-6-49 Detail of top wall in S room showing two beam tie-backs.

PR-6-50 Detail of arch openings in E wall of S room.

PR-6-51 Detail of arch openings in W wall of S room.